Serial No. 10/766,856 Amdt. dated May 8, 2006 Reply to Office action of February 8, 2006

- 2 -

## Amendments to the Specification:

Rewrite the paragraph beginning on page 7, line 22 as follows:

--The area of the hole section 111 of the main shutter 100 is lower than the area of the opening section of the seat of secondary control valve 106, so that when maximum discharge is commanded in the secondary control valve 102, the total decompression of the pressure chamber 100 110 may be achieved.--